

**Photos 7-13: Snow Creek, Mile~45.7. 15 October 2017.**



Photo 7. Upstream view to left bank, showing defoliated shrubs over wetted stream channel.



Photo 8. Defoliated red alder overhanging left bank downstream of rail bridge, and at least up to HWM of downstream left bank.





Photo 9. Downstream view of damaged Sitka willow, red alder and red-osier dogwood overhanging stream on right bank.





Photo 10. View of defoliated shrubs on upstream right bank.



Photo 11. Upstream view of right bank at rail bridge, showing damaged vegetation to HWM on both upstream and downstream sides.





Photo 12. View to left bank, showing defoliated red alder up to and beyond HWM.



Photo 13. Upstream view.